



促销中

ZYAMY WR55X10025 Temperature Sensor (Thermistor) for General Electric Refrigerator Replaces 914093, AP3185407, PS304103, WR50X10027

~~\$6.00~~ \$4.99

Cable length: 560mm/22in

Easy to install: fully suitable for most well-known brands (General Electric, hot), suitable models: A4425GDTABB, A4425GDTAWW, A4425GDTBBB, A4425GDTBWW, A4425GDTW, BSS25GFPAW, BSS25GFPAWW, BSS25GFPCSS, BSS25GFPCWW, BSS25GFPCWW, BSS25GFPCGFP, BSS25GFPCWW, BSS25GFPCWW, BSS25GFPCWW, BSS25JFTAWW, etc.

Replacement part number: 914093, AP3185407, WR50X10027, WR50X10034, WR50X10055, WR50X10067, WR55X10025B, WR55X10026, WR55X10027, WR55X10028, WR55X10030, WR55X10087, WR55X10088, WR55X10089, WR55X10367, WR55X10380, WR55X10661, WR55X10711, WR55X10735, WR55X10736, WR55X10737, WR55X10937, WR55X10938, WR55X10939, WR55X11121, WR55X11141, WR55X11150, PS304103.

1

加入购物车

分类: Appliances Parts & Accessories

描述

用户评论 (0)

描述

- Model number: WR55X10025 Refrigerator Temperature Sensor
- Suitable models: A4425GDTABB, A4425GDTAWW, A4425GDTBBB, A4425GDTBWW, A4425GDTW, BSS25GFPAW, BSS25GFPAWW, BSS25GFPCSS, BSS25GFPCWW, BSS25GFPCWW, BSS25GFPCGFP, BSS25GFPCWW, BSS25GFPCWW, BSS25GFPCWW, BSS25JFTAWW, etc.
- Replacement part numbers: 914093, AP3185407, WR50X10027, WR50X10034, WR50X10055, WR50X10067, WR55X10025B, WR55X10026, WR55X10027, WR55X10028, WR55X10030, WR55X10087, WR55X10088, WR55X10089 etc.
- Frost buildup, fridge section is too warm, fridge section is too cold, freezer section is too warm, freezer section is too cold, freezer is not defrosting.
- Package includes 1x WR55X10025 Temperature Sensor



You're viewing: ZYAMY WR55X10025 Temperature Sensor (Thermistor) for General Electric Refrigerator Replaces 914093, AP3185407, PS304103, WR50X10027
\$6.00 \$4.99

加入购物车

Address

2nd Floor, No. 13, Lane 7, Wenming Road, Humen Town, Dongguan, Guangdong, China,523900

Tel:+8615038110016

Email:info@dge-outstanding.com

© Dongguan E-outstanding Industrial Co., Ltd 2021

Built with Storefront & WooCommerce.

