



ACCESS SYSTEMS

RB502

Before you replace your plug-in transformer please confirm that the part number matches. If you cannot find the part number on your plug-in transformer, please check that the rating on the plug side matches the description below:


OUTPUT 14VAC 1430mA

GTO Access System
3121 Hartsfield Road • Tallahassee, FL 32303
1-800-543-4283
www.gtoaccess.com



0 90835 00530 1

MADE IN CHINA



3121 Hartfield Road • Tallahassee, FL 32303
www.gtoaccess.com • 800-543-4283

Made in China
for GTO Access Systems, LLC

90835 00530 1



TRANSFORMER

RB502

OUTPUT 14VAC 1430mA

Before you replace your plug-in transformer please confirm that the part number matches. If you cannot find the part number on your plug-in transformer, please check that the rating on the plug side matches the description below:

OUTPUT 14VAC 1430mA