

SPORTSWEAR

EQUIPMENT

CUSTOM















TENNIS / TENNIS RACKETS / BLADE /

BLADE 98 (16X19) V8 TENNIS RACKET

★★★☆☆ <u>(2)</u>

\$249.00

Add stringing below and the Wilson team will string the racket for you. Strung rackets ship in 3-5 days.

Cover Type: Uncovered







+ ADD STRINGS











DESCRIPTION

The Blade 98 (16x19) v8 pairs captivating design with a new layup to better accommodate the more modern, vertical swing path commonly used by competitive players. The headliner innovation, FORTYFIVE°, manages to increase both the flexibility and stability of the frame to lend supreme feel for the ball on every shot. Still characterized by its superior presence in the hands of the best players in the world, this evolution of Blade rewards aggressive, precise ball-strikers with a top-tier blend of connected-to-the-ball feel, torsional stability and color-shifting design to wow teammates and opponents alike.

Head (sq cm) Head (sq in) 98 Length (cm) 68,58 Length (in) 27 String Pattern 16X19 Strung balance 33 (cm)

Strung balance -4 (pts)

Strung weight 321

(grams)

Strung weight 11.32

Sub-Department Racket

Taper System 20.6 (mm)

32

Unstrung

balance (cm) Unstrung balance (pts)

Unstrung weight 305

Unstrung weight 10.76

FEATURES

Braided Graphite + Basalt

Elastic and reactive material combination improves the flex of a racket to increase ball contact with the strings for enhanced feel and greater control.

Parallel Drilling

Grommet construction provides a consistent, more forgiving string bed response while dramatically increasing the sweet spot.

Tapered grip lends better feel for top-handed grip placement on two-handed backhand.

Patent-protected frame layup produces more connected-to-the-ball feel while better complementing the more modern, vertical swing path. Material increases both flexibility and stability without compromise through the swing.

DirectConnect

Carbon fiber handle extends to directly connect with end cap for improved feel and enhanced torsional stability.

String pattern (16x19) allows strings to stretch more, generating greater capacity for power and spin

FORTYFIVE° increases flexibility and stability to produce a more connected-to-the-ball feel while better complementing the modern, vertical swing path used by most competitive players

DirectConnect extends the carbon fiber handle to connect directly to the end cap for improved feel and enhanced torsional stability

Dynamic, color-shifting elastic finish allows frame to morph between shades of green and copper

Top Grip Taper provides better feel for top-hand grip placement

Ergonomic End Cap yields improved comfort and playability

Braided Graphite + Basalt composition improves the flex of a racket to produce enhanced feel and control

Parallel Drilling provides a consistent, more forgiving string bed response

*Pros often customize the racket they use. Racket specifications on endorsed consumer models may vary from the models used by Pros for match-play.

REVIEWS

WRITE A REVIEW

0

1-2 of 2 Reviews

Sort by: Most Relevant





Helpful? Yes · 18 No · 13 Report

** Nick Sa · 4 months ago

Racquets great, customer service poor

I bought the new blade about a month ago and the topmost grommet fractured. I contacted customer service and said that it's not covered by warranty and I have to replace the bumper and grommet piece. That's fine, except they aren't available so now I have a broken grommet indefinitely. If getting this piece is anything like trying to order tennis balls, I'll never get to use the racquet again.
The wiser solution would be to send me the bumper and grommet set ASAP. I have ordered 8 racquets from wilson

this year. It's incredible they don't have a solution to this simple fix

Recommends this product X No

+ Comment



Benwa · a day ago

I've got 2 v8 blades since November 2021... I rotate them pretty evenly for even wear... Recently, I did a routine low volley and kissed the court surface and the grommet popped a big chunk off. Sounds like this is a common occurrence with these?

Helpful? Yes · O No · O Report

Strung · 3 days ago

Great frame but this also happened to me. Chipped the bumper guard off following some pretty light contact with the ground. I had never broken a bumper guard prior to this. Not sure what's going on with the quality there, but that is a huge bummer and as many have mentioned, the grommet sets are not yet available for this frame

Helpful? Yes · 1 No · 0 Report

<u>emem</u>_ · 13 days ago

so weird! same thing happened to me...i've never broken a grommet before either in 14+years of aggressive tennis playing...

Helpful? Yes · 3 No · 0 Report

★Top 500 Contributor

Helpful? Yes · 4 No · 2 Report

★★★★ sidd · a month ago

way better than v7 bruh

loved it bruh amazing racquet nice power amazing feel and precision way better than the previous model dud

Recommends this product $\,$ X $\,$ No

+ Comment

About Us Our Sites More Ways to Shop How can we help? Blog Wilson Find a Dealer Return Policy Louisville Slugger First Responder Discount Check Order Status Start a Return Limited Warranty DeMarini Military Discount EvoShield Careers Healthcare Worker Discount Shipping FAQ Contact Us Affiliate Program ATEC Tax Exempt Submit an Idea Luxilon Catalogs Wilson Team Shop Accessibility Patents Privacy Policy Terms of Use Terms of Sale CA Transparency Cookies Do Not Sell My Info

() y ()

↑ TOP