



POLESTAR
SOLAR LIGHT

C/NO:
MADE IN CHINA

POLESTAR
SOLAR LIGHT

C/NO:
MADE IN CHINA

ITEM NO: VCS-0041
QTY: PCS
N.W.: KGS
G.W.: KGS
MEAS: 60 76 51 43 CM

ITEM NO: VCS-0041
QTY: PCS
N.W.: KGS
G.W.: KGS
MEAS: 60 76 51 43 CM

ITEM NO: VCS-0041
QTY: PCS
N.W.: KGS
G.W.: KGS
MEAS: 60 76 51 43 CM

ITEM NO: VCS-0041
QTY: PCS
N.W.: KGS
G.W.: KGS
MEAS: 60 76 51 43 CM

POLESTAR
SOLAR LIGHT

C/NO:
MADE IN CHINA

POLESTAR
SOLAR LIGHT

C/NO:
MADE IN CHINA

ITEM NO: VCS-0041
QTY: PCS
N.W.: KGS
G.W.: KGS
MEAS: 60 76 51 43 CM

ITEM NO: VCS-0041
QTY: PCS
N.W.: KGS
G.W.: KGS
MEAS: 60 76 51 43 CM

POLESTAR
SOLAR LIGHT

C/NO:
MADE IN CHINA

POLESTAR
SOLAR LIGHT

C/NO:
MADE IN CHINA

ITEM NO: VCS-0041
QTY: PCS
N.W.: KGS
G.W.: KGS
MEAS: 60 76 51 43 CM

ITEM NO: VCS-0041
QTY: PCS
N.W.: KGS
G.W.: KGS
MEAS: 60 76 51 43 CM



Instruction Manual


Polestar Solar Step Light

1. Instruction:

This Solar light needs no mains power lead. It can turn on automatically at night and turn off in the day time.

2. Safety Information:


This product contains small parts that could be swallowed or inhaled by children. Keep this product and its packaging material away from children and pets. Do not use as a toy.



There is a risk of injury or damage if the instruction manual is not followed. The product is not to be handled improperly resulting in damage to the product.

3. Installation:

1. Turn the light on.
2. Measure a distance of 75mm from the top edge of the light.
3. Mark the position and drive the supplied screws in.



4. Battery change:



ITEM NO:VCS-0041
QTY: PCS
N.W.: KGS
G.W.: KGS
MEAS:60.7X51.5X43CM



C/NO:
MADE IN CHINA

ITEM NO:VCS-0041
QTY: PCS
N.W.: KGS
G.W.: KGS
MEAS:60.7X51.5X43CM



C/NO:
MADE IN CHINA