

**Showcase** 

Supplier Directory

**Industry News** 

Contact Us

Features

## **Powder Coating Booth**

<u>Powder Coating Supplier</u> <u>Directory</u>

Powder Coating Industry News

<u>Powder Coating Product</u> <u>Spotlight</u>

Powder Coating Equipment

<u>Used Powder Coating</u> <u>Equipment</u>

Powder Coating Systems

Powder Spray Booths

Powder Spray Guns

Powders Suppliers

**Industrial Cure Ovens** 

**How to Powder Coat** 

PCO VIP Supplier of the Month September 2019





Show all

## Powder Coating Booth

Published by 💄 pcoadmin at 🕓 December 12, 2015

ags 🔻 Categories 🔻



A powder coating booth is an enclosure that is designed to contain the powder application process. A recovery system is attached to the powder booth shell. The recovery system uses a fan to pull air into the booth and prevent the oversprayed powder from migrating out of the enclosure.

The simplest powder booths are designed for a single operator to manually apply powder to a stationary product. Other booths are designed so that parts can be conveyed through the enclosure.

Conveyorized systems may be designed for manual application from two sides, automatic application, or a combination of both, depending on the system requirements. The particular style, size and number of powder booths needed is related to the product size, the available space, the amount of capital and the volume of product to be coated.

Powder booth shells are occasionally made of painted steel but more often they are made of stainless steel, polypropylene, polycarbonate or other clear plastic, and a few are made of glass or polyethylene sheet.

Painted steel is adequate but there is some risk that the paint will chip off and contaminate the oversprayed powder in the reclaim system.



Stainless steel makes a very durable booth shell with a smooth

surface for ease of cleaning.

Plastic walled booths offer an easy to clean surface and the walls can allow some light to penetrate into the spray area and help illuminate the process. A nonconductive pma-Tron-X booth will collect less charged powder on the w

means that they can be easier to clean. It also means that they do not attract as much might otherwise be attracted to the part, so they provide a modest improvement in transfer

Want to be PCO VIP Supplier? <u>Click here</u>

## <u>Finishing Industry Calendar</u> of <u>Events</u>

Don't pay new equipment prices until you check the used powder coating equipment available here:

<u>Used Powder Coating</u>

<u>Equipment</u>

<u>List your used coating</u> <u>equipment FREE</u>

# Reach your buyers with an ad in the Super Specials Showcases

Check out <u>Powder Coaters</u> <u>Corner</u> for technical information on equipment, processes & application

Product Spotlight Cool new powder coating products

Glossary of powder coating terms

<u>Training Resources</u> Books, videos, classes

Join the PCO email group receive emails about equipment for sale, product sales, more

#### **Powder Coaters Manual**

Get a comprehensive how-to powder coat manual - The Powder Coating Institute

Find a coater in your area or list your company:

#### **Customcoaters.com**

Broadcast your company,
promote your products to over
coaters and finishers with
COEmail Program

The part size will influence the height and width of the booth and the required product opening. The opening size must allow the part to enter with proper clearance around the edges. In most cases, the clearance is 6" between the largest part and the edges of the opening.

In a conveyorized system, the booth shell should extend at least 18" above the opening to keep the



hook site well above the spray zone. The amount of opening in the booth will determine powder containment air requirements.

In order to contain the oversprayed powder, the collector fan is designed to provide 100-120 lineal feet per minute (Ifpm) of air velocity across all openings. Properly designed, the booth

will have even airflow throughout the enclosure and not interfere with

the coating process. Collector fan sizing must also

consider safety.

Each powder is rated with a lower explosion level (LEL) measured in oz/ft 3 . The booth must be designed with enough ventilation to keep the powder concentration level below 50% of the LEL. The number of guns and nominal powder output per gun determines concentration.

#### pcoadmin

### Related posts



<u>Powder Coating MDF-the</u> <u>Basics</u>

Read more



What Size Powder Coating Oven Do You Need?

Read more



New Technology Improves
First-Pass Powder
Coating Transfer
Efficiency

Read more



Suppliers, get your company listedin our exclusive Powder CoatingSupplier Directory - Choose where you list your company from categories specific to your business from the extensive list nbsp; List your company on PCO

<u>Product Spotlight</u> -Cool new powder coating products

- 3 Ways to sell your used equipment:
- 1.Broadcast your message to our 3000+ list of coaters (includes postings to all social media) \$100
- 2. Advertise your used equipment in the <u>Super</u>
  <u>Specials Showcases Rates</u>
  <u>vary</u>
- 3. List your used equipment <u>in</u> <u>the PCO Classifieds</u>- Free

Powder Coating Equipment Buying Guide

Directory of Business Services for Powder Coaters

Powder Coating
Industry News

Get a Listing
Advertise in the Showcases
Email Us
Industry News
Supplier Directory
Q&A Forum



Systems, Supplies, and Equipment for Today's Powder Coaters. Contact

130 Leathertree Lane Madison, AL 35758 256-837-1490 info@pcoaters.com

© 2019 PowderCoatingOnline.com. All Rights Reserved.

f ¥ in

