

Magnaset™ QP BINDER

DANGER! POISON!

COMBUSTIBLE LIQUID AND VAPOR.MAY BE FATAL IF INHALED.CAUSES EYE IRRITATION.MAY CAUSE SKIN AND RESPIRATORY TRACT IRRITATION. PROLONGED OR REPEATED CONTACT MAY DRY SKIN AND CAUSE DERMATITIS AND BURNS. MAY BE HARMFUL IF SWALLOWED OR ABSORBED THROUGH SKIN.

ATTENTION:

MAY AFFECT THE CENTRAL NERVOUS SYSTEM CAUSING DIZZINESS, HEADACHE OR NAUSEA.

FIRST AID:

IN CASE OF EYE CONTACT, immediately flush eyes with water for at least 15 minutes. Call a physician if irritation develops and persists. IN CASE OF CONTACT, immediately flush eyes or skin with plenty of water while removing contaminated clothing and shoes. Call a physician. Wash clothing before reuse. Decontaminate or discard contaminated shoes. IF INHALED, remove to fresh air and call a physician. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. IF SWALLOWED, DO NOT induce vomiting unless directed to do so by medical personnel. Never give anything by mouth to an unconscious person. Call a physician.

PRECAUTIONARY MEASURES:

Wash thoroughly after handling. Empty containers may contain hazardous product residues., Use or store with adequate ventilation. Keep workplace airborne concentrations below legal and recommended limits. Circumstances could require use of respiratory protection. Refer to applicable OSHA regulations., Keep away from heat and flame. Container and equipment used for handling, storage or transfer must be grounded and bonded.Avoid contact with eyes, skin and clothing. Wear chemical splash goggles, impervious gloves and other necessary protective equipment.Do not breathe vapor, spray or mist. Use only with adequate ventilation.Do not taste or swallow.

FIRE PROCEDURE:

In case of fire, use water spray (fog), foam, dry chemical or carbon dioxide.

SPILL PROCEDURE:

Contain and/or absorb spill with inert material (e.g. sand, vermiculite), then place in suitable container. Do not flush to sewer or allow to enter waterways. Use appropriate personal protective equipment. Dispose of wastes in accordance with applicable federal, state and local regulations.

DO NOT FREEZE. DO NOT MIX DIRECTLY WITH ACID IN ABSENCE OF SAND.

WARNING! This product contains a chemical known to the State of California to cause cancer.

	HMIS ¹	NFPA
Health	2	3
Flammability	2	2
Physical Hazards	1	
Instability		1
Specific Hazard		

¹HMIS, Registered trademark/service mark, National Paint and Coatings Association, Inc

NET Wt.: 499.99 LB 226.79 KG

Flash Point: 171 °F (77 °C)
Furfuryl alcohol , UN2874, PG III

Vapor Pressure: 5.07 hPa
VOC (Less H2O and Exempt): 783.18 g/l



ASK Chemicals L.P.
P.O. Box 395
Columbus, OH 43216
United States of America

Emergency Phone Number
1-855-ASK4YOU (1-855-275-4968)

™ Trademark, ASK Chemicals, registered in various countries

FOR INDUSTRIAL USE ONLY. BEFORE USE, REVIEW MATERIAL SAFETY DATA SHEET FOR FURTHER INFORMATION INCLUDING CHRONIC HEALTH EFFECTS.

Printed: January 5, 2012

Material:
154306

154306

154306
 BEFORE USE, REVIEW CONTAINER SIDE LABEL AND MATERIAL SAFETY DATA SHEET.
 NET Wt: 226.79 KG
 Magnaset™ QP BINDER